

Proyect:

Depths Check

DRAGADOS DEL CARIBE, S.A.S
Puerto de Rio Haina, Republica Dominicana

Supervised by:
Eng. Dickson Ml. Rivas Peralta

The information presented on this chart represents the results of a survey performed by Dragados del Caribe during March 2018 and can only be considered as indicating the conditions existing at the time.

Chart:
"Puerto de Santo Domingo"

Survey Date: March 22nd, 2018

Soundings in Meters and reduced to MLLW
UTM zone 19, Spheroid WGS-84
Scale : 1.3000