

Provect:

Depths Check

DRAGADOS DEL CARIBE, S.A.S
Puerto de Rio Haina, Republica Dominicana

Supervised by:

Eng. Dickson Ml. Rivas Peralta

The information presented on this chart represents the results of a survey performed by Dragados del Caribe during ***June 2019*** *and can only be considered as indicating the conditions existing at the time.*

Chart:

"Puerto de Santo Domingo"

Survey Date: ***June 29th, 2019***

Soundings in Meters and reduced to MLLW
UTM zone 19, Spheroid WGS-84
Scale 1: 3000